

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Renovation of Sri Shiva Temple at Barabank Bansajal GP

Work Code : OD/371/3565/121398/382326/00063991

Work Category : Religious Structures/ Religious Structures

District Name : Sambalpur

Block Name : Rairakhol

Gram Panchayat Name : Bansajal

Village Name : Barabank

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.11623151/-(Three lakh ninety nine thousand nine hundred ninety nine rupees one one six two three one five zero seven zero four paise only), vide TSR No OD/371/3565/121398/382326/00063991/TS dated: 17-11-2025.

Technical sanction given by : Khirabdi Tanaya Padhy, JE, Rairakhol.