

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of AWC Building at Pranadeipur under Hatiota GP

Work Code : OD/354/3380/117908/411363/00065527

Work Category : Building/ AWC

District Name : Ganjam

Block Name : Polosara

Gram Panchayat Name : Hatiota

Village Name : Pranadeipur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.99363971/- (Forty four thousand nine hundred ninety nine rupees nine nine three six three nine seven one paise only), vide TSR No OD/354/3380/117908/411363/00065527/TS dated: 25-11-2025.

Technical sanction given by : Sudhansu Sekhar Pattanaik, JE, Polosara.