

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Renovation of Shiva Temple at Kutasinga

Work Code : OD/371/3565/121406/382422/00065300

Work Category : Religious Structures/ Religious Structures

District Name : Sambalpur

Block Name : Rairakhol

Gram Panchayat Name : Luhapank

Village Name : Kutasingha

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.59770249/- (Three lakh ninety nine thousand nine hundred ninety nine rupees five nine seven seven zero two four eight seven paise only), vide TSR No OD/371/3565/121406/382422/00065300/TS dated: 25-11-2025.

Technical sanction given by : Hemangini Bhoi, JE, Rairakhol.