

TECHNICAL SANCTION FOR WORKS

Work Name : REPAIR AND RENOVATION OF DHABALESWAR TEMPLE AT MACHHAKUTA

Work Code : OD/344/3279/115651/404460/00068474

Work Category : Religious Structures/ Religious Structures

District Name : Angul

Block Name : Chhendipada

Gram Panchayat Name : Machhakuta

Village Name : Machhakuta

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 499999.00807536/-(Four lakh ninety nine thousand nine hundred ninety nine rupees zero zero eight zero seven five three six paise only), vide TSR No OD/344/3279/115651/404460/00068474/TS dated: 06-12-2025.

Technical sanction given by : LALATENDU SINGH, JE, Chhendipada.