

TECHNICAL SANCTION FOR WORKS

Work Name : Repair of Dahipur Pry School
Work Code : OD/346/3309/116320/393788/00075597
Work Category : Building/ Elementary School
District Name : Balasore
Block Name : Soro
Gram Panchayat Name : Manatri
Village Name : Dahipur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 149999.9965435/-(One lakh forty nine thousand nine hundred ninety nine rupees nine nine six five four three five zero zero zero two paise only), vide TSR No OD/346/3309/116320/393788/00075597/TS dated: 28-01-2026.

Technical sanction given by : Rojalin Jena , JE, Soro.