

## TECHNICAL SANCTION FOR WORKS

**Work Name :** IMPROVEMENT AND REPAIR OF CC ROAD FROM PRATAP SWAIN HOUSE TO NARAYANI TEMPLE, VILL- AINIPUR

**Work Code :** OD/355/3393/118231/397637/00067052

**Work Category :** Road/ CC Road

**District Name :** Jagatsinghpur

**Block Name :** Tirtol

**Gram Panchayat Name :** Sanara

**Village Name :** Ainpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 143787.88665626/- (One lakh forty three thousand seven hundred eighty seven rupees eight eight six six five six two five six three paise only), vide TSR No OD/355/3393/118231/397637/00067052/TS dated: 28-01-2026.

**Technical sanction given by :** RAMACHANDRA SARANGI, JE, Tirtol.