

TECHNICAL SANCTION FOR WORKS

Work Name : CONST. OF MAJHIDHAN MANDAP AT UPARSAHI DUNGURI BALI TALAKUSUMITA

Work Code : OD/361/3452/119449/386026/00067337

Work Category : Building/ Community Centre

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Baradapal

Village Name : Kusumita

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.987478/- (Two lakh ninety nine thousand nine hundred ninety nine rupees nine eight seven four seven eight paise only), vide TSR No OD/361/3452/119449/386026/00067337/TS dated: 20-02-2026.

Technical sanction given by : Kandarpa Palei, JE, Kendujhar Sadar.