

TECHNICAL SANCTION FOR WORKS

Work Name : CONST. OF BHOG MANDAP AT SILISUAN VILLAGE

Work Code : OD/361/3452/119456/385948/00068172

Work Category : Religious Structures/ Religious Structures

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Kandaraposi

Village Name : Silisuan

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 799999.99969811/- (Seven lakh ninety nine thousand nine hundred ninety nine rupees nine nine nine six nine eight one one paise only), vide TSR No OD/361/3452/119456/385948/00068172/TS dated: 18-03-2026.

Technical sanction given by : Sabyasachi Pradhan(AEE), Kendujhar Sadar.