

## TECHNICAL SANCTION FOR WORKS

**Work Name :** REPAIR AND MAINTENANCE OF ROAD FROM PATI BEHERA HOUSE TO BABA SINGH HOUSE AT SALPATALA

**Work Code :** OD/365/3487/120059/390594/00072232

**Work Category :** Road/ CC Road

**District Name :** Mayurbhanj

**Block Name :** Badasahi

**Gram Panchayat Name :** Purnachandrapur

**Village Name :** Purnachandrapur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 154075.88169433/- (One lakh fifty four thousand seventy five rupees eight eight one six nine four three three paise only), vide TSR No OD/365/3487/120059/390594/00072232/TS dated: 22-03-2026.

**Technical sanction given by :** GAGAN KUMAR MALLIK, JE, Badasahi.