

**Estimate Abstract**

**OD/362/3460/119605/407750/00017945 : Repair & Maintenance of Govt. Primary School, Dihapur  
Block : Bhubaneswar, Gram Panchayat : Itipur  
Created By:Sri Hemanta Samantaray**

SI No	Quantity	Unit	Rate in (Rs.)	Amount (Rs.)
1	<b>Painting : AR0901d (Priming one coat with inner surface primer of approved quality water-bound primer over plastering surfaces (Inner surface))</b> : Priming one coat with inner surface primer of approved quality water-bound primer over plastering surfaces including cost conveyance, taxes of all materials, labor and T&P required for the work complete as per direction of the Engineer-in-charge.			
	771.625	Square Meter	71.42865092951	55116.132773483
2	<b>Painting : AR0918fk (Finishing wall with two coat weather coat paint of approved shade in the outer surface of old work(Outside)(For repair and maintenance) .)</b> : Finishing wall with two coat weather coat paint of approved shade in the outer surface of old work to give an even shade including all costs of labour, Paint and Brushes required for the work, etc. complete and as per direction of Engineer-in-charge(Outside)(For repair and maintenance).			
	771.625	Square Meter	88.8830842875	68584.409913342

<b>Total Amount:</b>	123700.54268683
----------------------	-----------------

Provision for PH Work (+) @	
Provision for EI Work (+) @	
Provision for Contingency (+) @	1254
Display Citizen Board (+) @	425
Any Other Lumpsum (+) @	
Provision for survey investigation and quality control (+) @	

<b>Total Amount:</b>	125379.54268683
----------------------	-----------------

<b>Grand Net Total Amount</b>	125379.54268683
-------------------------------	-----------------

**Sri Hemanta Samantaray**  
**JE**  
**Bhubaneswar Block**

**Sri Niranjana Biswal**  
**AEE**  
**Bhubaneswar Block**

**Deviprasad Mohanty**  
**BDO**  
**Bhubaneswar Block**