

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Restoration of road from Kentalo Bangali sahi house Gopinathjew Temple under Kentalo GP.

Work Code : OD/350/3342/117096/399788/00017586

Work Category : Road/ CC Road

District Name : Cuttack

Block Name : Nischinta Koili

Gram Panchayat Name : Kentalo

Village Name : Kentala

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.99936672/-(One lakh ninety nine thousand nine hundred ninety nine rupees nine nine nine three six six seven two paise only), vide TSR No OD/350/3342/117096/399788/00017586/TS dated: 09-06-2025.

Technical sanction given by : Rajesh Kumar Sahu, JE, Nischinta Koili.