

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair & Renovation of Shiv Temple at Thuapadar

**Work Code :** OD/358/3409/118625/423422/00062737

**Work Category :** Religious Structures/ Religious Structures

**District Name :** Kalahandi

**Block Name :** Bhawanipatna

**Gram Panchayat Name :** Thuapadar

**Village Name :** Thuapadar

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 499178.22443744/- (Four lakh ninety nine thousand one hundred seventy eight rupees two two four four three seven four four one two paise only), vide TSR No OD/358/3409/118625/423422/00062737/TS dated: 31-10-2025.

**Technical sanction given by :** Juli Mali, JE, Bhawanipatna.