

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and restoration of Kedarpur -4 AWC

**Work Code :** OD/346/3309/116317/393979/00063520

**Work Category :** Building/ AWC

**District Name :** Balasore

**Block Name :** Soro

**Gram Panchayat Name :** Kedarpur

**Village Name :** Kedarpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.99952361/- (One lakh ninety nine thousand nine hundred ninety nine rupees nine nine nine five two three six one paise only), vide TSR No OD/346/3309/116317/393979/00063520/TS dated: 06-11-2025.

**Technical sanction given by :** Monalisa Pati , JE, Soro.