

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and restoration of Banamali sahi from babu singh house to Bijay singh house

Work Code : OD/346/3305/116236/393296/00063875

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Dharampur

Village Name : Baunsapala

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 89999.995989027/- (Eighty nine thousand nine hundred ninety nine rupees nine nine five nine eight nine zero two seven paise only), vide TSR No OD/346/3305/116236/393296/00063875/TS dated: 10-11-2025.

Technical sanction given by : BABITA BEHERA, JE, Nilgiri.