

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of AWC Building at Banthapalli-1 under Banthapalli GP

Work Code : OD/354/3380/117899/411490/00064858

Work Category : Building/ AWC

District Name : Ganjam

Block Name : Polosara

Gram Panchayat Name : Banthapalli

Village Name : Banthapalli

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.982453749/-(Forty four thousand nine hundred ninety nine rupees nine eight two four five three seven four nine paise only), vide TSR No OD/354/3380/117899/411490/00064858/TS dated: 18-11-2025.

Technical sanction given by : Subhasmita Patro, JE, Polosara.