

TECHNICAL SANCTION FOR WORKS

Work Name : Imp. of road with CC/Gr-II metalling from Sai Mandir to PMGSY road at Santa

Work Code : OD/348/3326/116686/395362/00064194

Work Category : Road/ CC Road

District Name : Bhadrak

Block Name : Chandabali

Gram Panchayat Name : Badaosita

Village Name : Badaostia

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 258991.16767649/-(Two lakh fifty eight thousand nine hundred ninety one rupees one six seven six seven six four nine paise only), vide TSR No OD/348/3326/116686/395362/00064194/TS dated: 02-12-2025.

Technical sanction given by : Ashashree Sahoo, JE, Chandabali.