

TECHNICAL SANCTION FOR WORKS

Work Name : Const of cc road from Shiba temple to babu sahi sala

Work Code : OD/361/3452/119451/386080/00068255

Work Category : Road/ CC Road

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Bodapalasa

Village Name : Bodapalasha

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.60111625/- (Two lakh ninety nine thousand nine hundred ninety nine rupees six zero one one one six two five paise only), vide TSR No OD/361/3452/119451/386080/00068255/TS dated: 12-12-2025.

Technical sanction given by : Manoj Kumar Sahoo, JE, Kendujhar Sadar.