

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Renovation of Maa Tarini temple near Basanti Mandap

Work Code : OD/346/3309/116313/393793/00069776

Work Category : Religious Structures/ Religious Structures

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Dahisade

Village Name : Dahisada

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 699999.99897505/-(Six lakh ninety nine thousand nine hundred ninety nine rupees nine nine eight nine seven five zero four nine nine paise only), vide TSR No OD/346/3309/116313/393793/00069776/TS dated: 17-12-2025.

Technical sanction given by : Nirmala Kanta Parida (AEE), Soro.