

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repairing of CC road from Binapani Pathagara to Rama Raja Temple via Ramachandra Panda house

**Work Code :** OD/356/3395/118278/402007/00070524

**Work Category :** Road/ CC Road

**District Name :** Jajpur

**Block Name :** Bari

**Gram Panchayat Name :** Bainsiria

**Village Name :** Bainsiria

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.63712297/- (One lakh ninety nine thousand nine hundred ninety nine rupees six three seven one two two nine seven paise only), vide TSR No OD/356/3395/118278/402007/00070524/TS dated: 17-12-2025.

**Technical sanction given by :** Swarnapriya Nayak, JE, Bari.