

TECHNICAL SANCTION FOR WORKS

Work Name : Construction Of Bhoga Mandap at Brundaban Bihari Temple, Chahata

Work Code : OD/356/3397/275260/401169/00070199

Work Category : Religious Structures/ Religious Structures

District Name : Jajpur

Block Name : Dharmasala

Gram Panchayat Name : Chahata

Village Name : Chahata

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.45114879/- (Two lakh ninety nine thousand nine hundred ninety nine rupees four five one one four eight seven nine paise only), vide TSR No OD/356/3397/275260/401169/00070199/TS dated: 23-12-2025.

Technical sanction given by : SIPRA SAHOO, JE, Dharmasala.