

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and Maintainance of road from Hrusikesh Nayak house to Saroj Sahoo house, vill- Mathasahi, GP- Srirampur

**Work Code :** OD/360/3440/119199/396277/00070686

**Work Category :** Road/ CC Road

**District Name :** Kendrapara

**Block Name :** Pattamundai

**Gram Panchayat Name :** Srirampur

**Village Name :** Palapatana

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 249645.27385721/- (Two lakh forty nine thousand six hundred forty five rupees two seven three eight five seven two one paise only), vide TSR No OD/360/3440/119199/396277/00070686/TS dated: 01-01-2026.

**Technical sanction given by :** BANDITA BEHURA, JE, Pattamundai.