

TECHNICAL SANCTION FOR WORKS

Work Name : Improvement/ Completion of Incomplete Kalyan Mandap at Bisipada

Work Code : OD/359/3430/118978/415494/00013539

Work Category : Building/ Kalyan Mandap

District Name : Kandhamal

Block Name : Phulbani

Gram Panchayat Name : Bisipada

Village Name : Bisipara

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 499999.00435117/- (Four lakh ninety nine thousand nine hundred ninety nine rupees zero zero four three five one one seven paise only), vide TSR No OD/359/3430/118978/415494/00013539/TS dated: 23-01-2026.

Technical sanction given by : SANTOSHI SAHOO, JE, Phulbani.