

TECHNICAL SANCTION FOR WORKS

Work Name : CONST OF BHOGA MANDAP LAXMI MANDIR AT UPARDIHA

Work Code : OD/361/3452/119471/386010/00068088

Work Category : Religious Structures/ Religious Structures

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Sankiri

Village Name : Upardiha

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.99319546/- (Two lakh ninety nine thousand nine hundred ninety nine rupees nine nine three one nine five four six paise only), vide TSR No OD/361/3452/119471/386010/00068088/TS dated: 29-01-2026.

Technical sanction given by : Ratikanta Lenka, JE, Kendujhar Sadar.