

TECHNICAL SANCTION FOR WORKS

Work Name : Renovation of Radhagobinda Temple at village Baneikala, Raikala GP

Work Code : OD/361/3452/119469/385959/00063983

Work Category : Religious Structures/ Religious Structures

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Raikala

Village Name : Baneikala

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 949999.98391843/-(Nine lakh forty nine thousand nine hundred ninety nine rupees nine eight three nine one eight four three paise only), vide TSR No OD/361/3452/119469/385959/00063983/TS dated: 14-02-2026.

Technical sanction given by : Sabyasachi Pradhan(AEE), Kendujhar Sadar.