

BLOCK PANCHAYAT DEVELOPMENT PLAN (BPDP) UNDER 15TH CFC (PS SHARE) OF PANCHAYAT SAMITI GUDARI FOR THE YEAR 2024-25

TOTAL ALLOTMENT RS. 49,04,010/- (TIED & UNTIED FUND)

UNTIED FUND = Rs. 19,61,604/- (40% out of total allocation of fund)

SI No	Name of the GP	Name of the Project	Estimated Cost	Category Tied/Untied
1	Madhuban	Improvement of road from RD road to Sibalingapur	230000	Untied
2	Karlaghati	Improvement of road from Papikal Khandia street to Church	520000	Untied
3	Sanahuma	Improvement of road from Sanyasiguda to Bentiguda	230000	Untied
4	Siriguda	Improvement of road from RD road to masani CC at Burukuda paika street	230000	Untied
5	Karlaghati	Improvement of road from Samberlendi to Haduguda Rasta	520000	Untied
6	Khariguda	Improvement of road from RD road to Banjanagar	231604	Untied
Total			1961604	

(Tied Fund -Rs (60% out of Allotment of Rs. 29,42,406/-)

7		25% tied fund for Repair & Maintenance of Tube Well	735602	Tied Fund
8		75% tied fund of PS shall be deposited with the DWSM A/c of the District	2206804	Tied Fund
Total			2942406	


Chairman
Gudari


Asst Executive Engineer
Gudari


Block Development Officer
Gudari

**BLOCK PANCHAYAT DEVELOPMENT PLAN (BPDP) UNDER 5TH SFC (PS SHARE) OF PANCHAYAT SAMITI
GUDARI FOR THE YEAR 2024-25**

TOTAL ALLOTMENT RS. 36,36,684/- (TIED & UNTIED FUND)

UNTIED FUND = Rs. 18,18,342/- (50% out of total allocation of fund)


Sl No	Name of the GP	Name of the Project	Estimated Cost	Category Tied/Untied
1	Gudari	Repair & Maintenance of Chairman Chamber, Gudari	300000	Untied
2	Gudari	Construction of Boundary Wall, Block Office, Gudari	700000	Untied
3	Gudari	Repair & Maintenance of Block Meeting Hall, Gudari	300000	Untied
4	Gudari	Repair & Maintenance of Chairman Quarter No 13-BC-3R, Gudari	250000	Untied
5	Gudari	Repair & Maintenance of Block Colony Staff Quarters	268324	Untied
Total			1818324	

(Tied Fund -Rs (50% out of Allotment of Rs. 18,18,342/-)

6		25% tied fund for Repair & Maintenance of Tube Well	454586	Tied Fund
7		75% tied fund of PS shall be deposited with the DWSM A/c of the District	1363756	Tied Fund
Total			1818342	


Chairman
Gudari


Asst Executive Engineer
Gudari


Block Development Officer
Block Gudari Gudari