

## **TECHNICAL SANCTION FOR WORKS**

**Work Name :** CONSTRUCTION OF BOUNDARY WALL AT BAURA UP SCHOOL AT BAURA UNDER RAJABASA GP

**Work Code :** OD/365/3490/120106/389157/00014362

**Work Category :** Other Infrastructure/ Boundary Wall

**District Name :** Mayurbhanj

**Block Name :** Baripada

**Gram Panchayat Name :** Rajabasa

**Village Name :** Baura

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 202036/-(two lakh two thousand thirty six rupees), vide TSR No OD/365/3490/120106/389157/00014362/TS dated: 19-12-2024.

**Technical sanction given by :** SWARNALATA BEHERA , JE, Baripada.