

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Maintenance of Rural Haat at Tandiki

Work Code : OD/364/3484/119979/430224/00013431

Work Category : Other Infrastructure/ Rural Haat

District Name : Malkangiri

Block Name : Malkangiri

Gram Panchayat Name : Tandiki

Village Name : Tondiki

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.76158426/- (Three lakh ninety nine thousand nine hundred ninety nine rupees seven six one five eight four two six zero zero four paise only), vide TSR No OD/364/3484/119979/430224/00013431/TS dated: 29-07-2025.

Technical sanction given by : Er. ABHIJIT SETHI(AEE), Malkangiri.