

## TECHNICAL SANCTION FOR WORKS

**Work Name :** REPAIR AND MAINTENANCE OF SUNDARIA KALYAN MANDAP

**Work Code :** OD/356/3397/118360/401299/00065400

**Work Category :** Building/ Kalyan Mandap

**District Name :** Jajpur

**Block Name :** Dharmasala

**Gram Panchayat Name :** Sundaria

**Village Name :** Sundaria

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.09508373/- (Two lakh ninety nine thousand nine hundred ninety nine rupees zero nine five zero eight three seven three two six paise only), vide TSR No OD/356/3397/118360/401299/00065400/TS dated: 01-12-2025.

**Technical sanction given by :** MONALISHA NAYAK, JE, Dharmasala.