

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const. of Kalyan mandap at Bisipada  
**Work Code :** OD/359/3430/118978/415494/00013527  
**Work Category :** Building/ Kalyan Mandap  
**District Name :** Kandhamal  
**Block Name :** Phulbani  
**Gram Panchayat Name :** Bisipada  
**Village Name :** Bisipara

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 999999.10738936/- (Nine lakh ninety nine thousand nine hundred ninety nine rupees one zero seven three eight nine three six paise only), vide TSR No OD/359/3430/118978/415494/00013527/TS dated: 15-12-2025.

**Technical sanction given by :** Laxmidhar Singh(AEE), Phulbani.