

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Maintenance of UPS Hinjalakuda

Work Code : OD/354/3385/118030/410964/00065253

Work Category : Building/ Elementary School

District Name : Ganjam

Block Name : Surada

Gram Panchayat Name : Hinjalakuda

Village Name : Hinjalakuda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 149999.09299502/- (One lakh forty nine thousand nine hundred ninety nine rupees zero nine two nine nine five zero one six nine paise only), vide TSR No OD/354/3385/118030/410964/00065253/TS dated: 17-12-2025.

Technical sanction given by : Kanheaya kar, JE, Surada.