

TECHNICAL SANCTION FOR WORKS

Work Name : Const of paver road from RD road to Behera sahi

Work Code : OD/356/3397/118360/401299/00070243

Work Category : Road/ Pavor Block

District Name : Jajpur

Block Name : Dharmasala

Gram Panchayat Name : Sundaria

Village Name : Sundaria

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 374999.90454507/- (Three lakh seventy four thousand nine hundred ninety nine rupees nine zero four five four five zero seven paise only), vide TSR No OD/356/3397/118360/401299/00070243/TS dated: 19-12-2025.

Technical sanction given by : MONALISHA NAYAK, JE, Dharmasala.