

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of paver block road from siva temple to badua amnavari temple at badua

Work Code : OD/353/3357/117449/414663/00067652

Work Category : Road/ Pavor Block

District Name : Gajapati

Block Name : Gosani

Gram Panchayat Name : Kharasandha

Village Name : Badua

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 529999.53457957/- (Five lakh twenty nine thousand nine hundred ninety nine rupees five three four five seven nine five seven one eight paise only), vide TSR No OD/353/3357/117449/414663/00067652/TS dated: 30-12-2025.

Technical sanction given by : SASMITA KUMARI JENA(AEE), Gosani.