

TECHNICAL SANCTION FOR WORKS

Work Name : repair and maintenance of T.M Academy Danar

Work Code : OD/361/3449/119389/387277/00072010

Work Category : Building/ Secondary School

District Name : Kendujhar

Block Name : Hatadihi

Gram Panchayat Name : Danar

Village Name : Danara

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 247999.9946035/- (Two lakh forty seven thousand nine hundred ninety nine rupees nine nine four six zero three five zero three seven paise only), vide TSR No OD/361/3449/119389/387277/00072010/TS dated: 04-01-2026.

Technical sanction given by : PRAFULLA CHANDRA BEHERA, JE, Hatadihi.