

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of cc road from Bishok Das sahi to kar sahi

Work Code : OD/360/3435/119066/396688/00074553

Work Category : Road/ CC Road

District Name : Kendrapara

Block Name : Derabish

Gram Panchayat Name : Khamala

Village Name : Bishok

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 161442.94252741/- (One lakh sixty one thousand four hundred forty two rupees nine four two five two seven four one paise only), vide TSR No OD/360/3435/119066/396688/00074553/TS dated: 13-01-2026.

Technical sanction given by : ABANI KUMAR MOHANTY, JE, Derabish.