

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of LAC Kedarpur

Work Code : OD/346/3309/116317/393979/00066158

Work Category : Building/ Livestock Aid Centre

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Kedarpur

Village Name : Kedarpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 64999.993658417/- (Sixty four thousand nine hundred ninety nine rupees nine nine three six five eight four one seven paise only), vide TSR No OD/346/3309/116317/393979/00066158/TS dated: 17-01-2026.

Technical sanction given by : Monalisa Pati , JE, Soro.