

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Maintenance of AWC Bijamal

Work Code : OD/358/3419/118817/422507/00073795

Work Category : Building/ AWC

District Name : Kalahandi

Block Name : Madanpur Rampur

Gram Panchayat Name : Mohangiri

Village Name : Bijamal

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44975.807002179/- (Forty four thousand nine hundred seventy five rupees eight zero seven zero zero two one seven eight five three paise only), vide TSR No OD/358/3419/118817/422507/00073795/TS dated: 25-01-2026.

Technical sanction given by : JE BEPARI, JE, Madanpur Rampur.