

TECHNICAL SANCTION FOR WORKS

Work Name : Completion of incomplete Kalyan Mandap at Tumudibandha

Work Code : OD/359/3433/119018/416964/00066157

Work Category : Building/ Kalyan Mandap

District Name : Kandhamal

Block Name : Tumudibandh

Gram Panchayat Name : Tumudibandh

Village Name : Tumudibandha

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 999975.01878162/- (Nine lakh ninety nine thousand nine hundred seventy five rupees zero one eight seven eight one six two two nine paise only), vide TSR No OD/359/3433/119018/416964/00066157/TS dated: 06-03-2026.

Technical sanction given by : Saroj Kumar Sabat(AEE), Tumudibandh.