

## TECHNICAL SANCTION FOR WORKS

**Work Name :** CONSTRUCTION OF CONCRETE FLOOR INFRONT OF LAXMINARAYAN MANDAP W NO 2

**Work Code :** OD/346/3299/116076/392564/00110083

**Work Category :** CD Work/ Drain Masonry or Cement Concrete

**District Name :** Balasore

**Block Name :** Baleshwar

**Gram Panchayat Name :** Kuradiha

**Village Name :** Sanadhanadi

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 326837.72320066/- (Three lakh twenty six thousand eight hundred thirty seven rupees seven two three two zero zero six six two zero six paise only), vide TSR No OD/346/3299/116076/392564/00110083/TS dated: 14-03-2026.

**Technical sanction given by :** ARUN KUMAR SWAIN, JE, Baleshwar.