

ADMINISTRATIVE/FINANCIAL SANCTION FOR WORKS

Work Name : Imp. of road with CC/Gr-II metalling from Bahu Haripur road to Sudam Behera house at Sarana Ichhapur

Work Code : OD/348/3326/116691/395418/00064189

Work Category : Road/ CC Road

District Name : Bhadrak

Block Name : Chandabali

Gram Panchayat Name : Bijayanagar

Village Name : Bijayanagar

Considering Importance and necessity of the work and resolute by the District, Bhadrak and Technically Approved / Sanctioned vide TSR No OD/348/3326/116691/395418/00064189/TS, Dt: 20-11-2025 the estimate of the proposed work has been accorded Administrative Sanction for Rs 258999.7754434/- (Two lakh fifty eight thousand nine hundred ninety nine rupees seven seven five four four three four paise only) vide Proceedings No. OD/348/3326/116691/395418/00064189/AS Dt: 20-11-2025.

Administrative sanction given by : BDO Chandabali(BDO), Chandabali.