

ADMINISTRATIVE/FINANCIAL SANCTION FOR WORKS

Work Name : Imp. of road with CC/Gr-II metalling from Sai Mandir to PMGSY road at Sainda

Work Code : OD/348/3326/116686/395362/00064194

Work Category : Road/ CC Road

District Name : Bhadrak

Block Name : Chandabali

Gram Panchayat Name : Badaosita

Village Name : Badaostia

Considering Importance and necessity of the work and resolute by the District, Bhadrak and Technically Approved / Sanctioned vide TSR No OD/348/3326/116686/395362/00064194/TS, Dt: 10-12-2025 the estimate of the proposed work has been accorded Administrative Sanction for Rs 258991.16767649/- (Two lakh fifty eight thousand nine hundred ninety one rupees one six seven six seven six four nine paise only) vide Proceedings No. OD/348/3326/116686/395362/00064194/AS Dt: 10-12-2025.

Administrative sanction given by : BDO Chandabali(BDO), Chandabali.