

Raja Munda
Kordla

Bolani



Dhadrachhi

Barbil

Joda



Biletpaala

Deojhar

Badahundule

Jugachikhar
Karkapur

Kandara

Chakka

Basuderpur


Ramchandrapur

Danpur

Rimuli → NH 20 →

Thunpura

Keojhar



Turumanga

(Erandei
sand quarry)

Badapose

Gopalpur

Badapose
quarry

(ALL THE DIMENSIONS
ARE NOT IN SCALE)