

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Improvement Of Road From PMGSY Road Belada Jagannath Mandir To Harihar Tripathy House, W-1, Khandatada G.P.

**Work Code :** OD/348/3323/116636/394812/00016228

**Work Category :** Road/ CC Road

**District Name :** Bhadrak

**Block Name :** Bhadrak

**Gram Panchayat Name :** Khandatada

**Village Name :** Khandatara

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 143787.94845977/- (One lakh forty three thousand seven hundred eighty seven rupees nine four eight four five nine seven seven three nine paise only), vide TSR No OD/348/3323/116636/394812/00016228/TS dated: 25-07-2025.

**Technical sanction given by :** GOBINDA CHANDRA PRADHAN, JE, Bhadrak.