

TECHNICAL SANCTION FOR WORKS

Work Name : Improvement Of Road From Chanduli Mallick Sahi To Mallia S Lurce Gate At Kulararichuan

Work Code : OD/350/3337/116966/400084/00018414

Work Category : Road/ CC Road

District Name : Cuttack

Block Name : Cuttacksadar

Gram Panchayat Name : Kulararichuan

Village Name : Kulararichuan

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 95575.760638619/-(Ninety five thousand five hundred seventy five rupees seven six zero six three eight six one nine paise only), vide TSR No OD/350/3337/116966/400084/00018414/TS dated: 01-08-2025.

Technical sanction given by : Samata Debata, JE, Cuttacksadar.