

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and Maint of Road with CC / Gr-II metalling from Prabhakar Behera House to Kalandi Sahoo house , Godijharia , Bhiruda

**Work Code :** OD/350/3345/117170/398981/00062606

**Work Category :** Road/ CC Road

**District Name :** Cuttack

**Block Name :** Tigiria

**Gram Panchayat Name :** Bhiruda

**Village Name :** Godijharia

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 190444.73360926/-(One lakh ninety thousand four hundred forty four rupees seven three three six zero nine two six paise only), vide TSR No OD/350/3345/117170/398981/00062606/TS dated: 21-11-2025.

**Technical sanction given by :** Mihir Kumar Sethy, JE, Tigiria.