

TECHNICAL SANCTION FOR WORKS

Work Name : Repair of AWC at Sirki
Work Code : OD/359/3425/118918/415830/00065798
Work Category : Building/ AWC
District Name : Kandhamal
Block Name : G.Udayagiri
Gram Panchayat Name : Mallikapadi
Village Name : Siriki

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 99999.555362854/- (Ninety nine thousand nine hundred ninety nine rupees five five five three six two eight five four paise only), vide TSR No OD/359/3425/118918/415830/00065798/TS dated: 01-12-2025.

Technical sanction given by : PRAMOD KUMAR NAYAK, JE, G.Udayagiri.