

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const Of cement concrete Road From Rama Senapati House To Tarini Mandap

**Work Code :** OD/356/3397/118348/401382/00070958

**Work Category :** Road/ CC Road

**District Name :** Jajpur

**Block Name :** Dharmasala

**Gram Panchayat Name :** Madhusudanpur

**Village Name :** Madhusudan Pur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.99079103/- (Three lakh ninety nine thousand nine hundred ninety nine rupees nine nine zero seven nine one zero three paise only), vide TSR No OD/356/3397/118348/401382/00070958/TS dated: 20-12-2025.

**Technical sanction given by :** SWAPNIL BEHERA, JE, Dharmasala.