

TECHNICAL SANCTION FOR WORKS

Work Name : REPAIR AND MAINTENANCE OF AWC AT RAMACHANDRAPUR MUNDA SAHI

Work Code : OD/361/3451/119447/385420/00068086

Work Category : Building/ AWC

District Name : Kendujhar

Block Name : Joda

Gram Panchayat Name : Kandara

Village Name : Ramachandrapur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.990100109/- (Forty four thousand nine hundred ninety nine rupees nine nine zero one zero zero one zero nine paise only), vide TSR No OD/361/3451/119447/385420/00068086/TS dated: 30-12-2025.

Technical sanction given by : SARITA ROUT, JE, Joda.