

## TECHNICAL SANCTION FOR WORKS

**Work Name :** REPAIR AND MAINTENANCE OF GOVT. UPS ARAPATA

**Work Code :** OD/365/3487/120052/390650/00072940

**Work Category :** Building/ Elementary School

**District Name :** Mayurbhanj

**Block Name :** Badasahi

**Gram Panchayat Name :** Madhapur

**Village Name :** Arapata

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 99999.7366557777/-(Ninety nine thousand nine hundred ninety nine rupees seven three six six five five seven seven six five five paise only), vide TSR No OD/365/3487/120052/390650/00072940/TS dated: 12-01-2026.

**Technical sanction given by :** ANATA KISHORE NAYAK, JE, Badasahi.