

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of Dahipur AWC
Work Code : OD/346/3309/116320/393788/00069788
Work Category : Building/ AWC
District Name : Balasore
Block Name : Soro
Gram Panchayat Name : Manatri
Village Name : Dahipur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.99632461/- (One lakh ninety nine thousand nine hundred ninety nine rupees nine nine six three two four six one paise only), vide TSR No OD/346/3309/116320/393788/00069788/TS dated: 28-01-2026.

Technical sanction given by : Rojalin Jena , JE, Soro.