

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Renovation of Raitikar Mangala CC

Work Code : OD/356/3403/118510/400578/00071250

Work Category : Building/ Community Centre

District Name : Jajpur

Block Name : Sukinda

Gram Panchayat Name : Pingala

Village Name : Raitikar

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 199999.98807173/- (One lakh ninety nine thousand nine hundred ninety nine rupees nine eight eight zero seven one seven two eight eight paise only), vide TSR No OD/356/3403/118510/400578/00071250/TS dated: 31-01-2026.

Technical sanction given by : Sabita Soren, JE, Sukinda.